



भारतीय मानक ब्यूरो
BUREAU OF INDIAN STANDARDS

9 Bhadhur Shah Zafar Marg
New Delhi - 110002
Tel. No. 23230856, 23230131
Fax No. 23234062
Email: mdd3@bis.org.in
Web: <http://www.bis.org.in>

SPEED POST

Our Ref: MDD-III/IS 1554 (I), 8783, 9857, 9968, 14255, 7098 (I),
2465, 5950, 14494

28-02-2013

To,
All licensees of IS 1554 (I), 8783, 9857, 9968, 14255, 7098 (I), of MDD-III
2465, 5950, 14494

Dear Sir,

From time to time we are updating yourselves through various circulars sent & also hosted on BIS website under licensee/applicant's section for improvement of operation of certification marks licence for product held by you. While examining various correspondence received, your manufacturing material, it is seen that the marking which is not covered as per specifications IS 1554 (I), 8783, 9857, 9968, 14255, 7098 (I), 2465, 5950, 14494 is also being used on the product as well as packing labels/drums. One such example is 'an ISO 9001 company' marked on cable, or on label/drums with BIS standard mark.

Your attention is drawn that certification under ISO 9001 is related to quality system management adopted by your organization and is nowhere relevant to the product. Therefore, Cable manufactured by you should not have such marking and if you have been using such marking you are advised to discontinue this with immediate effect and send confirmation to us in this respect at the earliest.

संज्ञानाद

भवदीय,

(राकेश चन्द्र)

वैज्ञानिक एफ मुवि-III